

WORK SMARTER,
NOT HARDER WITH
**DELPHI VEHICLE
TECHNICAL
INFORMATION**

FAULT CODE: P018C

**RENAULT KADJAR
1.5 DCI K9K 2017**

Delphi

 **PHINIA**


WORKING ON A RENAULT KADJAR WITH THE ENGINE LIGHT ON?



Delphi



 **PHINIA**



FAULT CODE: P018C

Delphi

 **PHINIA**

SYMPTOM:

Engine warning light ON

CAUSE:


**Faulty low-pressure
fuel system sensor**

SOLUTION:

**Check sensor voltage - should be
1.13v at idle speed & 1.77v at 2000rpm.
If this is incorrect, replace the sensor**

YOUR SHORTCUT TO EXPERT VEHICLE INSIGHTS

ACCESS
YOUR
VTI
TODAY!



Delphi

 **PHINIA**