

WORK SMARTER,
NOT HARDER WITH
**DELPHI VEHICLE
TECHNICAL
INFORMATION**

FAULT CODE: B200F

VW GOLF 2.0 GTI


Delphi

 **PHINIA**

**IS THE LANE DEPARTURE
WARNING FOR YOUR
VW GOLF 2.0 GTI (2021)
NOT WORKING?**

Delphi

 **PHINIA**



FAULT CODE: B200F

Delphi

 **PHINIA**

SYMPTOM:

Lane departure warning currently not available

CAUSE:

Faulty forward-view camera system software

SOLUTION:

Using Pass-Thru and ODIS, update the Forward-facing camera software

YOUR SHORTCUT TO EXPERT VEHICLE INSIGHTS

ACCESS
YOUR
VTI
TODAY!



Delphi

 **PHINIA**