

A woman with dark hair tied back, wearing a dark jacket, is looking down at a rugged tablet computer. She is holding a stylus in her right hand and the tablet in her left. The background is a solid blue color.

WORK SMARTER, NOT HARDER WITH **DELPHI VEHICLE TECHNICAL INFORMATION**

FAULT CODE: 2A1100

BMW X3 2.0i

Delphi

 **PHINIA**

The image shows the rear left side of a white BMW X3 2.0i. The car's taillight is illuminated with a red glow, and the engine warning light is visible on the rear window. The background is a blurred sunset or sunrise scene with warm orange and yellow tones. The text "IS YOUR BMW X3 2.0i ENGINE WARNING LIGHT ON?" is overlaid in white, bold, sans-serif font.

**IS YOUR BMW X3 2.0i
ENGINE WARNING
LIGHT ON?**

Delphi

 **PHINIA**

SYMPTOM:


**Engine warning light,
engine vibration**

CAUSE:

Faulty vibration damper

SOLUTION:

**Check and replace vibration damper -
if fault code is still present,
change alternator**



FAULT CODE: 2A1100

Delphi

 **PHINIA**

SYMPTOM:

**Engine warning light,
engine vibration**

CAUSE:


Faulty vibration damper

SOLUTION:

**Check and replace vibration damper -
if fault code is still present,
change alternator**

YOUR SHORTCUT TO EXPERT VEHICLE INSIGHTS

ACCESS
YOUR
VTI
TODAY!



Delphi

 **PHINIA**